

# LANCIA LAMBDA BEARINGS

<b>BACK AXLE</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Pinion</b>	<b>102431</b>	<b>N307</b>		<b>Roller</b>	<b>2</b>
<b>Pinion</b>	<b>102461</b>			<b>Thrust</b>	
<b>Crown wheel</b>	<b>102401</b>	<b>6211</b>		<b>Ball</b>	
<b>Crown wheel</b>	<b>102491</b>			<b>Ball/Thrust</b>	
<b>Half shaft</b>	<b>102402</b>	<b>6308</b>		<b>Ball</b>	<b>2</b>

<b>BRAKES</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Brake cam shaft</b>	<b>102409</b>			<b>Ball</b>	<b>8</b>
<b>Brake cross shaft</b>	<b>102410</b>			<b>Ball</b>	<b>7</b>
<b>Brake cross shaft (front)</b>	<b>102411</b>	<b>6200</b>		<b>Ball</b>	
<b>Front brake pulley box</b>	<b>102411</b>	<b>6200</b>		<b>Ball</b>	<b>2</b>

<b>ENGINE</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Cam vertical drive</b>	<b>102406</b>	<b>6307</b>		<b>Ball</b>	<b>2</b>
<b>Cam vertical drive</b>	<b>102408</b>	<b>7305</b>	<b>1176</b>	<b>Thrust</b>	<b>2</b>
<b>Cam follower</b>	<b>10307/9/13</b>			<b>Roller</b>	<b>8</b>
<b>Dynamo drive</b>	<b>102415</b>	<b>98206</b>		<b>Ball</b>	<b>2</b>
<b>Fan spindle</b>	<b>102413</b>	<b>6301</b>	<b>2B</b>	<b>Ball</b>	
<b>Fan spindle</b>	<b>102414</b>	<b>6302</b>	<b>3B</b>	<b>Ball</b>	
<b>Dynamo</b>	<b>101860</b>				
<b>Clutch roller</b>	<b>102419</b>			<b>Ball</b>	<b>2</b>
<b>Clutch spigot</b>	<b>102492</b>			<b>Ball/thrust</b>	

# LANCIA LAMBDA BEARINGS

<b>GEARBOX</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Primary shaft</b>	<b>102420</b>	<b>98307</b>		<b>Ball</b>	
<b>Primary shaft</b>	<b>102431</b>	<b>N307</b>	<b>1164</b>	<b>Roller</b>	
<b>Primary/Output shaft</b>	<b>102433</b>	<b>N303</b>		<b>Roller</b>	
<b>Primary/Output shaft</b>	<b>10839</b>			<b>Thrust</b>	
<b>Output shaft</b>	<b>102403</b>	<b>6307</b>		<b>Ball</b>	
<b>Layshaft</b>	<b>102432</b>	<b>N305</b>	<b>1165</b>	<b>Roller</b>	<b>2</b>
<b>Speedo drive</b>	<b>102412</b>	<b>EN8</b>		<b>Magneto</b>	<b>2</b>

<b>PROP SHAFT</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Cardan coupling</b>	<b>102417</b>	<b>98202</b>		<b>Ball</b>	<b>4</b>
<b>Cardan bracket</b>	<b>102418</b>	<b>6306</b>	<b>7B</b>	<b>Ball</b>	

<b>STEERING BOX</b>					
<b>Bearing</b>	<b>Lancia no.</b>	<b>SKF no.</b>	<b>RIV no.</b>	<b>Type</b>	<b>no. off</b>
<b>Inner gear</b>	<b>112450</b>	<b>1203</b>		<b>Self aligning</b>	
<b>Outer gear</b>	<b>112451</b>	<b>1206</b>		<b>Self aligning</b>	
<b>Front worm</b>	<b>112493</b>			<b>Ball/Thrust</b>	
<b>Rear worm</b>	<b>112494</b>			<b>Ball/Thrust</b>	
<b>Steering column support</b>	<b>112410</b>			<b>Ball</b>	